Please attach this sheet to the items which you are returning

Unit 7, Fieldhouse Park, Old Fieldhouse Lane Huddersfield, West Yorkshire, HD2 1FA T 01484 511882 E accounts@automint.uk W automint.uk





Ensure that all items below are correct. If they are not or if you are returning some items which are missing then please telephone 01484 511882

## Customer

Parkmore Truck and Bus Parts Limited Unit 10 Parkmore Industrial Estate Longmile Road Dublin 12 Ireland D12 X585 Account: TRUC41

Fax / Email:

accounts@automint.uk

Date: 02 October 25

Returns No.

82177

Customer Returns No. Automint Error

Reason

**Automint Error** 

Comments

Mis-pick on S/O 822302 - Should have sent 1 x T0125A actually sent 1 x T0381A

Quantity	Details	Price Each	Handling	Line Total	Handling	Line Total
1	T0381A Torque Rod	£82.54	0.0%	£82.54		

## **Delivery Address**

Parkmore Truck and Bus Parts Limited Unit 10 Parkmore Industrial Estate Longmile Road Dublin 12 Ireland D12 X585 Delivery: Sales Person To Collect

Fixed Penalty:

Total Weight: 11 KG

Received at Automint

Date

Signed by

Print name

