Automint Ltd

Unit 7, Fieldhouse Park, Old Fieldhouse Lane Huddersfield, West Yorkshire, HD2 1FA T 01484 511882 F 01484 511883 E accounts@automint.uk W automint.uk

Please attach this sheet to the items which you are returning





Ensure that all items below are correct. If they are not or if you are returning some items which are missing then please telephone 01484 511882

Customer

Truck Parts (N. Wales)
Unit 3, Mochdre Creamery Trade Parc
Station Road
Mochdre
Conwy
LL28 5EF

Account: TRUC36

Fax / Email:

returns@truckpartsnw.co.uk

Date: 09 July 25

Returns No.

80661

Customer Returns No.

Reason

Warranty

Comments

Warranty - CA13LCH / YV2RT40C8FB739488 / Fitted - 13/6/25 / Failed - 20/6/25 / Fault - Cusotmer reported the spring caused the wheel alignment was being affected, fitted genunie Volvo spring and issue was resolved

Quantity	Details	Price Each	Handling	Line Total	Handling	Line Total
1	TS1577B Truck Spring	£315.48	0.0%	£315.48		

Delivery Address

Truck Parts (N. Wales)
Unit 3, Mochdre Creamery Trade Parc
Station Road
Mochdre
Conwy
LL28 5EF

Delivery: Customer To Return

Fixed Penalty:

Total Weight: 63 KG

Received at Automint

Date

Signed by

Print name

